

2000 Toyota 4Runner Maintenance Sheet

Date/Mileage	Service Performed	Misc. Notes
April 2005 - 70,563	Tow hitch and tow wiring installed at dealer	Toyota service history
September 2005 - 78,991	Transmission assembly overhauled - Precision Toyota of Tucson	Toyota service history
August 2008 - 90,768	Shocks/struts replaced, front/rear diff oil changed, belts changed - Desert Toyota of Tucson	Toyota service history
November 3, 2013 - 94,000	Previous owner purchased, passed emissions	
February 2014 - 98,000	Rock sliders	Custom, bolt on
August 2014 - 105,000	Front bumper, winch, lights, painted flares with bedliner	BanditRunner bumper design
February 2015 - 115,000	Lift Installed - Bilstein 5100, Eibach 620lb front coils, OME 890 rear coils, Monroe Land Cruiser rear shocks. Toytec 1" front diff drop kit	
March 2015 - 117,000	Clutch replaced - Exedy OEM replacement. Flywheel shaved	
June 2016 - 135,000	Alternator replaced	O'Reilly Auto Parts alternator
August 2016 - 138,000	Replaced plugs and wires with Denso plugs and NGK wires. Replaced driver's side CV axle for torn boot	
May 2017 - 151,000	Falken 285/75/16 Wildpeak AT3W installed on all four wheels. Wheel spacers added. Rear driveshaft replaced with new U-joints.	
July 2017 - ??	CEL for evap box for broken nipple on charcoal canister. Replace nipple, CEL goes away.	
November 2017 - ??	AZ State Emissions pass	
May 2018 - 164,000	Coolant flush with Toyota red coolant, new radiator cap, new Centric rotors and Wagner pads	
June 2018 - 165,000	Keaton Burleson purchased. Discount Tire lifetime Roadforce balance purchased. Tires balanced.	
July 2018 - 168,000	TPS replaced when TPS code was thrown. Code was cleared and went away, but TPS was replaced with OEM part anyway. Throttle body and MAF sensor cleaned with MAF sensor cleaner. Seafoam was run through intake. Registered in the state of Tennessee. Fuel filter replaced. Yakima 48" Crossbars added to replace OEM roof rack bars. Original dealer license plate surround added	Old TPS in center console in Toyota box.
October 2018 - 172,000	Upper control arm bushings and lower control arm bushings replaced. Lower ball joints were replaced with Senkei 555 components. New tie rod ends and new tie rod end boot for driver's side. Replaced shift bushing. Replaced passenger side CV axle. New thermostat and gasket. New sway bar bushings and end links, front and rear. Upper ball joints replaced. Timing belt and water pump replaced. Toyota red coolant refilled. New idler pulley. New fan clutch and fan.	
November 2018 - 173,000	2001 OEM 4Runner horns installed (one of the original ones stopped functioning). Gas gauge sending assembly cleaned to fix non-working gas gauge. Original fuel pump and sock replaced with Denso components. Toyota clutch spring replaced with a linear brake spring to improve clutch feel. Original upstream O2 sensor and air filter replaced with Denso components. Replaced rear hatch lift struts with Monroe lift struts. Rubber Walmart mats replaced with "Limited" 4Runner cloth mats. Blinker and side marker functionality swapped for better visibility. ECT button wired in to antenna controls. Single climate control bulb replaced with OEM bulb. Front skid plate repainted. OEM flasher unit replaced with EP35 flasher unit to fix hyper-flash	OEM/Original flasher unit in center console in EP35 box.
Pre-sale November 2018 - 174,000	Interior cleaned with a steam cleaner/stain puller. Valve cover gaskets replaced. Throttle cable adjusted.	

Misc. Useful Information

VIN	JT3HN86R2Y0286572
Next Oil Change Due	Approximately 2000 miles
Tire Size	285/75 R16 (lifted) - 265/70 R16 (stock)
Paint	Toyota White - Single Stage
Rear Locking Differential	Electric, can only be engaged in 4Low